


# AEM WB to SCT X3 Wiring Diagram

## Autometer Wideband Gauge To SCT X3 Wiring



|              | PIN OUT        |        |
|--------------|----------------|--------|
| Signal Name  | IEEE 1394 6P/M | Cable  |
| +5 Ext       | 1              | White  |
| Gnd          | 2              | Black  |
| Analog 1     | 3              | Orange |
| Analog 1 Gnd | 4              | Blue   |
| Analog 2     | 5              | Red    |
| Analog 2 Gnd | 6              | Green  |

Be sure to check the wire colors with your cable. Wire colors can vary from cable to cable.